To: Jimenez, Jose[JIMENEZ.JOSE@EPA.GOV]; Gardner, Allison[Gardner.Allison@epa.gov];

Graham, Allison[Graham.Allison@epa.gov]; Isales, Daniel[Isales.Daniel@epa.gov]; Crutchley,

Gerard[Crutchley.Gerard@epa.gov]; Young, Justin[Young.Justin@epa.gov]

From: Jimenez, Jose

Sent: Thur 7/25/2013 1:23:16 PM

Subject: Super Salvage

Hi Everyone,

The purpose of this meeting is to discuss the next steps concerning Super Salvage. Please note the meeting will start at 1:15 pm. As you know, EPA has visited the location twice, here is what we know:

Super Salvage is a scrap metal facility located in Washington, DC.

http://www.epa-otis.gov/cgi-bin/get1cReport.cgi?tool=otis5&IDNumber=110002503693

On February 20, 2013, Allison Graham, an EPA inspector, visited the site to determine compliance with facility's Industrial Stormwater requirements.

On May 28-29, 2013, Jerry and Justin visited Super Salvage and took several samples. Waiting for sample results.

Some of my questions are:

Ex. 7(a)